

## Rework SOP for GPS issue of Freerunner (GTA02)

Soldering a 10pF capacitor between PIN5 and PIN6 at SD card slot without taking off the case as the below picture showed.

